



Conference Agenda

June 14-17, 2021

This agenda is currently in draft for the The Signs, Lights and Markings (SLAM) Conference.
All agenda items will be held at the Intercontinental Buckhead Atlanta.

Monday, June 14 | Airfield Marking Professional (AMP) Certificate Program

7:30am	Airfield Marking Professional (AMP) Certificate Program Registration Opens
8:00am - 4:00pm	AMP Certificate Program - Day 1 Windsor Ballroom AB

Tuesday, June 15 | SLAM Welcome Reception

8:00am - 4:00pm	AMP Certificate Program - Day 2 Windsor Ballroom AB
12:00pm - 7:00pm	SLAM Conference Registration Open
2:00pm - 5:00pm	Exhibitor Setup
5:30pm - 7:00pm	Welcome Reception with Exhibitors Windsor Ballroom CDE

Wednesday, June 16 | SLAM Conference - Day 1

7:00am - 8:00am	Breakfast with Exhibitors Windsor Ballroom CDE
8:00am - 8:45am	Welcome, ALPA Presentation - A Pilot's Perspective on Visual Aids Windsor Ballroom AB
9:00am - 10:00am	Presentation - Watch Your Azimuth Windsor Ballroom AB
10:00 am - 10:30 am	Networking Break with Exhibitors Windsor Ballroom CDE
10:30am - 11:30am	Presentation - Airfield Asset Management Strategy Windsor Ballroom AB
12:00pm - 1:00pm	Lunch with Exhibitors Windsor Ballroom CDE

Breakout Sessions

Signs & Lights - Hope Room

Markings - Trippe Room

1:00pm - 1:45pm	Presentation - LED's and Construction Challenges Hope Room	Presentation - Causing Friction Trippe Room
2:00pm - 2:45pm	Presentation - Solar Systems Hope Room	Presentation - Making What You Have Work for Your Airport Trippe Room
2:45pm - 3:15pm	Networking Break with Exhibitors Windsor Ballroom CDE	
3:15pm - 4:00pm	Presentation - Construction Req's for Lighting Hope Room	Presentation - The Meaning of Cleaning Trippe Room

Thursday, June 17 | SLAM Conference - Day 2

7:00am - 8:00am	Breakfast with Exhibitors Windsor Ballroom CDE
8:15am - 9:00am	Mark Kaminski Award Presentation Windsor Ballroom AB
9:00am - 10:00am	Presentation - Common Part 139 Discrepancies and Industry Solutions Patrick Rogers, Lead Airport Certification Safety Inspector, FAA Southern Region Windsor Ballroom AB
10:15am - 10:45am	Networking Break with Exhibitors Windsor Ballroom CDE
11:00am - 11:45am	Presentation - Airport Operations Self-Inspections, Draft AC 150/5200-18D Windsor Ballroom AB
12:00pm - 1:00pm	Lunch with Exhibitors Windsor Ballroom CDE
1:00pm	Exhibitor Strike

Breakout Sessions

Signs & Lights - Hope Room

Markings - Trippe Room

1:00pm - 1:45pm	Presentation - FAA Req's for Back-Up Generators Hope Room	Presentation - Pretormed Thermoplastic, Life Cycle Cost Analysis Trippe Room
2:00pm - 2:45pm	Presentation - TBA Hope Room	Presentation - Good Housekeeping Trippe Room

Combined Session

Windsor Ballroom AB

3:00pm - 3:45pm	Presentation - "Keeping Contractors Accountable" Roundtable Windsor Ballroom AB
4:00pm	Closing Remarks, Adjourn Windsor Ballroom AB